

NG Road Inspection Report for July 13, 2017

Mercury Lane – Coming down Mercury, ditch work is needed on the right side. More ditch work is needed on the lower portion. Electrical lines are close to the side of the road, so the ditches must be dug further back.

Venus Way – Upper Venus has not received any ditch work and the road surface appears to be untouched. Lower Venus received some ditch work, fresh gravel and grading. Ditch work is still needed at the beginning of Venus.

Capricorn Drive from Venus Way to the Cul de Sac – Incomplete ditch work seen on both sides of the road. Gravel and dirt mounds need to be smoothed out.

Capricorn Drive from Venus Way to Gemini Road – Adequate ditch work, the exception of which is, the front of Sandoval's property on Capricorn. No ditch provided here. Water from her property often washes over Capricorn and into adjoining neighbor's yards. The ditch on the uphill portion of Capricorn empties into her yard. It should channel water down along the road and to the culvert in her driveway.

Gemini Road to Orion Way - Incomplete and messy ditch work noted along the right side of Gemini, before Sally Muto's driveway. Past Sally's driveway, the ditches are adequate for a short distance on the right and left sides of the road. Then they stop, so ditch work is incomplete. Looks like two loads of fresh gravel were dumped on Gemini.

Orion Way – Ditches are good, except for in front of the Gough's property. They stop before that property and then pick up after that property. The Gough's property also encroaches on the GLA Road Easement. One building may violate the original setback requirements, as well.

Upper Orion Way past Evening Star Lane – Remains untouched to the very end. No ditch work and apparently no road grading either.

Gemini Road to Starlight Lane – Light ditch work but incomplete.

Gemini Road past Starlight Lane – Grading, but no ditch work had been done. What looked like new gravel and rolling after a rainstorm, was upon closer inspection, last year's gravel. Lots of protruding rocks remain on upper Gemini. Grader tracks were seen farther up, at the junction of Gemini Road and Caspari Way.

Also observed, were twelve (12) new reflectors and poles on Upper Gemini Road.

Sirius Drive (gravel portion) – Excellent grading and ditch work. Most definitely, the best roadwork completed in 2017 for North Glastonbury. If all the gravel roads were done this well the job could be considered complete.

Taurus Road from Sirius Drive and up the hill – Left side fine, right side needs more ditch work. No ditches from parcels 43/45 on the left side. Mizzi got very nice ditches. The opposite side to Hilarion Road needs ditch work.

Aries Drive (gravel portion) – Road was graded and rolled, no ditch work except on a small section the left side, by the 4-way intersection with Sirius Drive.

Sirius Drive (paved) – Excellent ditch work along the church-owned portion until the turn downhill which leads into GLA property. Both sides were very well done.

Pisces Way – No ditch work and no gravel. Light grading was done, but only for a short distance.

Aquarius Lane – No ditch work, except for a short 50 foot stretch, where Aquarius meets the north end of Capricorn Drive. No gravel or grading either.